



Industrie Service

Choose certainty.  
Add value.

# REPORT

## WRG 406

### DIN EN 13141-11

<b>Test laboratory</b>	TÜV SÜD Industrie Service GmbH Center of Competence for Refrigeration and Air Conditioning Air Conditioning and Ventilation
<b>Test object</b>	"Aircare AF +" mechanical controlled supply air ventilation system from the company Thesan SpA, Via Torino 25 10050 Chiussa di San Michele (To) Italy
<b>Customer</b>	Thesan SpA, Via Torino 25 10050 Chiussa di San Michele (To) Italy
<b>Scope of assignment</b>	Tests according to DIN EN 13141-11:2015-07
<b>Date of receipt of test object</b>	2015-04-15
<b>Test period</b>	2015-04-17 - 2016-06-09
<b>Test location</b>	Munich Olching
<b>Expert</b>	Heiko Mirring
<b>Test specification</b>	DIN EN 13141-11:2015-07 DIN EN ISO 5801:2012-11

Date: 2016-06-23

Our reference:  
IS-TAK3-MUC/ mr

Document:  
wrg406 Thesan Aircare AF+  
Report 13141-11-160623-  
mrkl.docx

Order-No.. 2553442

This document consists of  
8 Pages + 23 Appendices  
Page 1 of 8

Excerpts from this document may  
only be reproduced and used for  
advertising purposes with the  
express written approval of  
TÜV SÜD Industrie Service GmbH.

The test results refer exclusively  
to the units under test.



Headquarters: Munich  
Trade Register Munich HRB 96 869  
VAT ID No. DE129484218  
Information pursuant to Section 2(1)  
DL-InfoV (Germany) at  
www.tuev-sued.com/imprint

Supervisory Board:  
Karsten Xander (Chairman)  
Board of Management:  
Ferdinand Neuwieser (CEO),  
Dr. Ulrich Klotz, Thomas Kainz

Phone: +49 89142 4461-501  
Fax: +49 89142 4461-530  
[www.tuev-sued.de/is](http://www.tuev-sued.de/is)



TÜV SÜD Industrie Service GmbH  
Center of Competence for  
Refrigeration and Air Conditioning  
Air Conditioning and Ventilation  
Ridlerstrasse 65  
80339 Munich  
Germany